


Mundelein – A665

Improvements include


- Installation of additional fuses and trip savers to reduce customer outage exposure due to tree issues and enhanced tree trimming



Mundelein – A665

Improvements include

- Enhanced tree trimming



Mundelein – A6627

Improvements include

- Installation of additional fuses and trip savers to reduce customer outage exposure due to tree issues and . Installation of HENDRIX spacer cable A overhead installation of covered, bundled primary wire that can withstand tree branches and small tree contact. Proven to reduce outages by 75-85%.



